



By:



PLC-TX Wiring Color Code

| <u>Wire Color</u> | <u>Output</u> | <u>Function</u> |
|-------------------|---------------|-----------------|
| • Orange | J1 | Work Lights |
| • Grey | J2 | Auxiliary |
| • Green | J3 | Right Arrow |
| • Yellow | J4 | Left Arrow |
| • Black | J5 | Center Out |
| • Blue | J6 | Strobe |